

---

## BELZONA® PROTECTION TO BUTANE TANK BASE

---

### CUSTOMER

International Petroleum Company - Australia

### APPLICATION DATE

2002

### APPLICATION SITUATION

Insulated tank containing Butane at -6°C (21°F).

### PROBLEM

Corrosion at base of tank. At same time, timber supports were being renewed.

### PRODUCTS

Belzona® 3211 (Lagseal)

### SUBSTRATE

Steel, Concrete and Timber

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

### BELZONA FACTS

Belzona application creates a flexible, waterproof but microporous seal at junction of tank and base to provide long-term corrosion protection.

### PHOTOGRAPHS

1. General view of the tank.
2. Preparation of tank and base underway. Tank jacked up ready to install new timbers.
3. Application underway.
4. Application being completed.

